

# GHT SERIES

# Box way type Turning lathe GHT355



### SUZHOU GUDWAY CNC EQUIPMENT CO.,LTD

Add: No. 21 Xiexin Road, New District, Suzhou City, Jiangsu Province, China.

Tel: +86-0512-65580060

Email: info@gudwaycnc.com

Web: http://www.gudwaycnc.com



Equipped with a 15-inch chuck, the GHT 355 has a high-torque spindle and the largest Z-axis travel in its class, which can process large workpieces to meet the various processing needs of customers.













# High rigidity structure High Rigidity Irough FEM (finite elemalysis), the bed is ont:

Through FEM (finite element analysis), the bed structure was optimized to ensure the high rigidity of the bed structure.

# 2 Low center of gravity

30° inclined bed low center of gravity structure, with a wider bed, improved stability.

# 3 Stability

The design of two-axis all-hard rail structure, wide guide surface and wide span of guide rail spacing, makes the force area larger, more uniform force, and improves the processing stability.







# High productivity

# 1 Spindle


Equipped with high-performance spindles that minimize vibration and thermal displacement during spindle rotation, high-torque spindles provide superior machining capabilities

# 2 Turret


The newly designed turret, driven by an efficient servo motor, ensures its machining capability and stable tool changing performance at high speeds.



X-axis 24m/min Z-axis 30m/min



# Spindle power-torque diagram



# chuck



Chuck size: 15 inch

Turning diameter (mm)	Ø380
Max. turning diameter (mm)	Ø481
Bar machining diameter (mm)	Ø102

# Convenience of operation

### Convenience of operation

The newly designed operating panel enhances ease of operation with universal buttons and positioning.



10.4 inch display

•USB&PCMCIA card (ST)

New ergonomic design Easy to install button switch additional options

# 2 Tool position viewing device

The tool position visual device installed on the upper end of the chuck can easily see the moving shaft and the tool position during processing, without the need to pass the control panel, the tool change operation will be more convenient, and effectively improve the operation convenience.





### Simple software

raise productivity
Reduce non-cutting time

### 10%

The non-cutting time during machining is greatly reduced, thus guaranteeing maximum productivity.



Tool monitor OP



During the cutting operation, abnormal loads caused by tool wear or damage are detected and alarms are triggered to prevent further damage.

# Rocker arm type operating panel


The operation panel is redesigned and the rocker arm type operation panel is selected to meet the operating convenience of the operator to the greatest extent.





# Excellent processing performance

(Motor power: 45/25 kW)



Machining Outer diameter turning (high speed)		
Chip removal rate	565 cm <sup>3</sup> /min	
Cutting speed	225 m/min	
Feedrate	0.35 mm/rev	
Spindle speed	269 r/min	
Cutting depth	7 mm	



Machining outer diameter turning (low speed)		
Chip removal rate	617 cm³/min	
Cutting speed	156 m/min	
Feedrate	0.55 mm/rev	
Spindle speed	187 r/min	
Cutting depth	7 mm	



Machining inside diameter turning	60	
Cutting speed		280 m/min
Feedrate		0.3 mm/rev
Spindle speed		1486 r/min
Cutting depth	(2)	3 mm
Tool length	72	4.0 D



U drill (2 axes)	
Chip removal rate	799 cm³/min
Cutting speed	200 m/min
Feedrate	0.32 mm/rev
Spindle speed	1273 r/min
U Drill diameter	15 mm




# Environmental-friendly

# 1 LED work light and condition light

Even in the state of low voltage, LED lights can still work stably in a highly efficient state, and the service life is 10 times that of halogen lamps.

LED working light



LED condition light



# Auto off

After 10 minutes of no operation on the operation panel, the working light will be automatically turned off.

ON





### 3 Auto off

After 10 minutes of no operation on the operation panel, the spindle, servo motor, chip remover motor, and coolant tank motor will automatically shut down, saving energy and protecting the equipment.

Coolant tank motor



The spindle and servo motor stop and turn off



Motor of the chip remover stops and turns off



# Optional configurations



chip conveyor	material	Note
hinge type	steel	The most typical type of chip conveyor is suitable for steel production of chips of 30mm or longer length
Drag type	cast iron	The conveyor with magnet is suitable for the processing of cast iron with small and fine chips





Drag type



# Optional



oil skimmer



Automatic OP tool setting gauge



Chuck blow






oil mist collector





Hydraulic center frame




If you need to turn longer parts, you can use various types of hydraulic center frames (single, double supported or double supported)




Basic parameters

### Machining range



# Tool interferogram


GHT355






Basic parameters

# Tool system



# Machine size

GHT355





Basic parameters

# Parameter GHT**355**

			//	<u> </u>
Parameter		ITEM	UNIT	GHT <b>355</b>
		Machine bed Max Turning Dia	mm	Ø740
GHT <b>355</b>	Machine capacity	Saddle Max Turning Dia	mm	Ø555
		Recommended turning diameter	mm	Ø380
		Max. turning dia	mm	Ø481
		Max truning length	mm	1270
		Bar machining diameter	mm	Ø102
_		Max pindle speed	r/min	2500
		Spindle nose	ASA	A2-11
	Spindle	Spindle through hole diameter	mm	Ø115
		bearingdia(front)	mm	Ø160
		Max. spindle Torque	N∙m	1123
		X-axis	mm	260(19.5+240.5)
	Travel	Z-axis	mm	1350
_	F	X-axis	m/min	24
	Fast move	Z-axis	m/min	30
	.0	Tool number	ea	10
	- 4.0.	Cylindrical tool dimensions	mm	25 x 25
	Turret	Boring bar diameter	mm	Ø50
		Transposition time	S	0.15
_	0	Center diameter	mm	Ø100
4	Tailstock	Center taper		MT#5
and a		Center stroke	mm	100
1/1/2	Motor	Spindle motor power	kW	22 / 18.5
	Power	Power supply (rated capacity)	Kva	28.83
		Height	mm	1930
off	Size	Floor area Length	mm	4675
		Width	mm	1840
		Weight	kg	6900
STA	ANDARD		OPTIONA	• {}OP

### **STANDARD**

### OPTIONAL

	Hydraulic chuck&Rotary cylind@ondition light		
	Soft clamp	Foot switch	
	Chuck clamp detection switch	Front door interlock	
	Live tip	Safety nameplate	
	Standard tool holder	Leveling bolts & pad iron	
	Hydraulic power unit	Toolbox	
	Cutting fluid supply equipmen	t	
	Lubricating oil equipment Iron filings and safety metal	Machine instructions and manuals	
	Working light	.0`	
n,	Ongwayene		

Chip remover Auto tool setting (manual) Chip truck Clamp clean blowing device Hard clasp Clamp clean water blowing Automatic power off Auto door Air gun Programmable tailstock Water gun Dead center for tail seat(MT#4) Oil skimmer Center frame (hydraulic type) Additional holder&bush \* Special chuck



## NC specification

FANUC i Plus Series

Basic parameters	
Shaft control	
Control path 1 path	
Control axis number 2 axis	
Control axis number 2 axes at the same time Control shaft disassembly	
Reverse clearance compensation Reverse clearance compensation for each qu	ick feed and cut
Chamfer start/stop	ion icca aria cat
Advanced feedforward control	
Position tracking	
Servo HRV controls HRV2	
Imperial/metric conversion	
Interlock all axes/shafts	
Minimum input increment 0.001/0.0001 mm /i	nch
Minimum setting UNITC ISXC	
Mechanical lock all axes/shafts	
Mirroring	
Overpass	
Servo off	
Storage stroke detection 1 Abnormal Load Detection	
Emergency stop	
Position switch	
Operations	
Autorun (memory)	
MDI run	
Buffer register	
DNC run	
Use a memory card for a DNC A CR	F card and a dedicated
	r are required
Scheduling features	
Empty run	V4 938
Incremental feed	X1,X10,X100
Handwheel feed interrupt	
JOG feed Manual intervention and return	
Hand wheel feed	
Manually return to the reference point	
Program number retrieval	
Program restart	
Sequence number search	
Interpolation function	
Return to first reference Point Manual, G28	
Return to second reference point G30	
Return to reference points 3 and 4	
Naninterpolating	
Exact way to stop	
Tapping method	
Method of cutting	
Accurate stopping	
Arc interpolation CO2 CO3	
Arc interpolation G02,G03	
Continuous Thread Cutting	
Continuous Thread Cutting Polygon machining	
Continuous Thread Cutting	
Continuous Thread Cutting Polygon machining Cylindrical interpolation	
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause	
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip	
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00	
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27	
Continuous Thread Cutting Polygon machining Cylindrical Interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed	
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cut cycle back	
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cut cycle back Torque limit skip	
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting	
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function	
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function Automatic acceleration/deceleration	
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function Automatic acceleration/deceleration Cutting feed rate reed	G9R
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function Automatic acceleration/deceleration Cutting feed rate reed Feed per minute	G98 G99
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function Automatic acceleration/deceleration Cutting feed rate reed Feed per ninute Feed per turn	G98 G99
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function Automatic acceleration/deceleration Cutting feed rate reed Feed per minute Feed per turn Feed speed multiplier (10%UNIT)	
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function Automatic acceleration/deceleration Cutting feed rate reed Feed per minute Feed speed multiplier (10%UNIT) JOG multiplier (10%UNIT)	G99
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cutting/synchronous feed Thread cutting/synchronous feed Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function Automatic acceleration/deceleration Cutting feed rate reed Feed per minute Feed per minute Feed speed multiplier (10%UNIT) JOG multiplier (10%UNIT) Manual feed per turn	G99 0-200%
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function Automatic acceleration/deceleration Cutting feed rate reed Feed per minute Feed per minute Feed speed multiplier (10%UNIT) JOG multiplier (10%UNIT) Manual feed per turn Multiplier cancel	G99 0-200% 0-2,000 mm/min
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function Automatic acceleration/deceleration Cutting feed rate reed Feed per minute Feed speed multiplier (10%UNIT) JOG multiplier (10%UNIT) Manual feed per turn Multiplier cancel Quick feed multiplier	G99 0-200%
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function Automatic acceleration/deceleration Cutting feed rate reed Feed per minute Feed per minute Feed speed multiplier (10%UNIT) JOG multiplier (10%UNIT) Manual feed per turn Multiplier cancel Quick feed multiplier Goulck feed multiplier Fast feed speed	G99 0-200% 0-2,000 mm/min F0, 50100%
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function Automatic acceleration/deceleration Cutting feed rate reed Feed per minute Feed speed multiplier (10%UNIT) JOG multiplier (10%UNIT) Manual feed per turn Multiplier cancel Quick feed multiplier Fast feed speed Fast feed bell type acceleration and decelerat	G99 0-200% 0-2,000 mm/min F0, 50100%
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function Automatic acceleration/deceleration Cutting feed rate reed Feed per minute Feed per minute Feed speed multiplier (10%UNIT) JOG multiplier (10%UNIT) Manual feed per turn Multiplier cancel Quick feed multiplier Fast feed speed Fast feed bel lype acceleration and decelerat Auxiliany/spindle speed function	G99 0-200% 0-2,000 mm/min F0, 50100%
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function Automatic acceleration/deceleration Cutting feed rate reed Feed per ninute Feed per turn Feed speed multiplier (10%UNIT) JOG multiplier (10%UNIT) Manual feed per turn Multiplier cancel Quick feed multiplier Fast feed speed function Spindle positioning	G99 0-200% 0-2,000 mm/min F0, 50100%
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cutting/synchronous feed Thread cutting/synchronous feed Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function Automatic acceleration/deceleration Cutting feed rate reed Feed per minute Feed per minute Feed speed multiplier (10%UNIT) JOG multiplier (10%UNIT) Manual feed per turn Multiplier cancel Quick feed multiplier Fast feed speed Fast feed speed Fast feed speed Fast feed positioning Actual spindle speed output	G99 0-200% 0-2,000 mm/min F0, 50100%
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function Automatic acceleration/deceleration Cutting feed rate reed Feed per minute Feed speed multiplier (10%UNIT) JOG multiplier (10%UNIT) Manual feed per turn Multiplier cancel Quick feed multiplier Fast feed speed Fast feed bell type acceleration and decelerat Auxiliary/spindle speed function Spindle positioning Actual spindle speed output Auxiliary function locks	G99 0-200% 0-2,000 mm/min F0, 50100%
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function Automatic acceleration/deceleration Cutting feed rate reed Feed per minute Feed speed multiplier (10%UNIT) JOG multiplier (10%UNIT) Manual feed per turn Multiplier cancel Quick feed multiplier Fast feed speed Fast feed bell type acceleration and decelerat Auxiliary/spindle speed function Spindle positioning Actual spindle speed output Auxiliary/spindle speed output Auxiliary/spindle speed output Auxiliary/spindle speed output Auxiliary function locks Constant weekly speed control	G99 0-200% 0-2,000 mm/min F0, 50100%
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function Automatic acceleration/deceleration Cutting feed rate reed Feed per ninute Feed per turn Feed speed multiplier (10%UNIT) JOG multiplier (10%UNIT) Manual feed per turn Multiplier cancel Quick feed multiplier Fast feed speed Fast feed bell type acceleration and decelerat Auxiliary/spindle speed function Spindle positioning Actual spindle speed output Auxiliary function locks Constant weekly speed control Auxiliary function M 8-bit number	G99 0-200% 0-2,000 mm/min F0, 50100%
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function Automatic acceleration/deceleration Cutting feed rate reed Feed per minute Feed per minute Feed speed multiplier (10%UNIT) JOG multiplier (10%UNIT) Manual feed per turn Multiplier cancel Quick feed multiplier Fast feed speed Fast feed speed Fast feed speed Fast feed bell type acceleration and decelerat Auxiliary/spindle speed output Auxiliary function locks Constant weekly speed control Auxiliary function S5 digits	G99 0-200% 0-2,000 mm/min F0, 50100%
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function Automatic acceleration/deceleration Cutting feed rate reed Feed per minute Feed per minute Feed speed multiplier (10%UNIT) JOG multiplier (10%UNIT) Manual feed per turn Multiplier cancel	G99 0-200% 0-2,000 mm/min F0, 50100%
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function Automatic acceleration/deceleration Cutting feed rate reed Feed per ninute Feed per turn Feed speed multiplier (10%UNIT) JOG multiplier (10%UNIT) Manual feed per turn Multiplier cancel Quick feed multiplier Fast feed speed Fast feed bell type acceleration and decelerat Auxiliary/spindle speed function Spindle positioning Actual spindle speed output Auxiliary function locks Constant weekly speed control Auxiliary function M 8-bit number Spindle serial output S5 digits Spindle lenating fication 0-150%	G99 0-200% 0-2,000 mm/min F0, 50100%
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cutting Feed function Automatic acceleration/deceleration Cutting feed rate reed Feed per minute Feed per minute Feed per minute Feed speed multiplier (10%UNIT) JOG multiplier (10%UNIT) Manual feed per turn Multiplier cancel Quick feed multiplier Fast feed speed function Spindle positioning Actual spindle speed output Auxiliary function locks Constant weekly speed control Auxiliary function M 8-bit number Spindle serial output S5 digits Spindle serial output S5 digits Spindle output switching	G99 0-200% 0-2,000 mm/min F0, 50100%
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function Automatic acceleration/deceleration Cutting feed rate reed Feed per minute Feed per minute Feed speed multiplier (10%UNIT) JOG multiplier (10%UNIT) Manual feed per turn Multiplier cancel Quick feed multiplier Fast feed speed Fast feed speed function Spindle positioning Actual spindle speed output Auxiliary/spindle speed function Spindle positioning Actual spindle speed output Auxiliary function M 8-bit number Spindle function S5 digits Spindle magnification 0-150% Spindle magnification 0-150% Spindle napping Program input	G99 0-200% 0-2,000 mm/min F0, 50100%
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function Automatic acceleration/deceleration Cutting feed rate reed Feed per ninute Feed per turn Feed speed multiplier (10%UNIT) JOG multiplier (10%UNIT) Manual feed per turn Multiplier cancel Quick feed multiplier Fast feed speed function Spindle speed function Spindle speed function Spindle speed function Spindle speed output Auxiliary/spindle speed output Auxiliary function locks Constant weekly speed control Auxiliary function S5 digits Spindle serial output S5 digits Spindle output switching Rigid tapping Program input Absolute/incremental instructions	G99 0-200% 0-2,000 mm/min F0, 50100%
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cutting/synchronous feed Thread cutting/synchronous feed Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function Automatic acceleration/deceleration Cutting feed rate reed Feed per minute Feed per minute Feed speed multiplier (10%UNIT) JOG multiplier (10%UNIT) Manual feed per turn Multiplier cancel Quick feed multiplier Fast feed speed Fast feed speed Fast feed speed Fast feed speed function Spindle positioning Actual spindle speed output Auxiliary function locks Constant weekly speed control Auxiliary function M 8-bit number Spindle serial output S5 digits Spindle magnification 0-150% Spindle magnification 0-150% Spindle output switching Rigid tapping Program input Absolute/incremental instructions Append user macro public variables	G99 0-200% 0-2,000 mm/min F0, 50100%
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function Automatic acceleration/deceleration Cutting feed rate reed Feed per minute Feed speed multiplier (10%UNIT) JOG multiplier (10%UNIT) Manual feed per turn Multiplier cancel Quick feed multiplier Fast feed speed Fast feed bell type acceleration and decelerat Auxiliary/spindle speed function Spindle positioning Actual spindle speed output Auxiliary function M 8-bit number Spindle function S digits Spindle serial output S5 digits Spindle magnification 0-150% Spindle magnification 0-150% Spindle magnification 0-150% Spindle speed muput Absolute/incremental instructions Append user macro public variables Fixed loop for drilling	G99 0-200% 0-2,000 mm/min F0, 50100%
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function Automatic acceleration/deceleration Cutting feed rate reed Feed per ninute Feed per turn Feed speed multiplier (10%UNIT) JOG multiplier (10%UNIT) Manual feed per turn Multiplier cancel Quick feed multiplier Fast feed speed Fast feed speed function Spindle positioning Actual spindle speed output Auxiliary/spindle speed output Auxiliary function locks Constant weekly speed control Auxiliary function M 8-bit number Spindle serial output S5 digits Spindle serial output S5 digits Spindle output switching Rigid tapping Program input Absolute/incremental instructions Append user macro public variables Fixed loop for drilling Single shape fixed cycle	G99 0-200% 0-2,000 mm/min F0, 50100%
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cutting/synchronous feed Thread cutting/synchronous feed Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function Automatic acceleration/deceleration Cutting feed rate reed Feed per minute Feed per minute Feed speed multiplier (10%UNIT) JOG multiplier (10%UNIT) Manual feed per turn Multiplier cancel Quick feed multiplier Fast feed speed Fast feed speed Fast feed speed Fast feed speed function Spindle positioning Actual spindle speed output Auxiliary function locks Constant weekly speed control Auxiliary function S5 digits Spindle serial output S5 digits Spindle serial output S5 digits Spindle serial output S5 digits Spindle magnification 0-150% Spindle nagnification 0-150% Spindle output switching Rigid tapping Program input Absolute/incremental instructions Append user macro public variables Fixed loop for drilling Single shape fixed cycle Arc radius R specified	G99 0-200% 0-2,000 mm/min F0, 50100%
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function Automatic acceleration/deceleration Cutting feed rate reed Feed per minute Feed per minute Feed speed multiplier (10%UNIT) JOG multiplier (10%UNIT) Manual feed per turn Multiplier cancel Quick feed multiplier Fast feed speed Fast feed speed Fast feed bell type acceleration and decelerat Auxiliary/spindle speed output Auxiliary function locks Constant weekly speed control Auxiliary function S5 digits Spindle serial output S5 digits Spindle serial output S5 digits Spindle magnification 0-150% Spindle magnification 0-150% Spindle output switching Rigid tapping Program input Absolute/incremental instructions Append user macro public variables Fixed loop for drilling Single shape fixed cycle Arc radius R specified Control input/output	G99 0-200% 0-2,000 mm/min F0, 50100%
Continuous Thread Cutting Polygon machining Cylindrical interpolation Pause High Speed skip Straight interpolation G01 Multiple thread cutting Positioning G00 Return to reference point to detect G27 Thread cutting/synchronous feed Thread cutting/synchronous feed Thread cutting/synchronous feed Thread cutting/synchronous feed Thread cut cycle back Torque limit skip Variable pitch thread cutting Feed function Automatic acceleration/deceleration Cutting feed rate reed Feed per minute Feed per minute Feed speed multiplier (10%UNIT) JOG multiplier (10%UNIT) Manual feed per turn Multiplier cancel Quick feed multiplier Fast feed speed Fast feed speed Fast feed speed Fast feed speed function Spindle positioning Actual spindle speed output Auxiliary function locks Constant weekly speed control Auxiliary function S5 digits Spindle serial output S5 digits Spindle serial output S5 digits Spindle serial output S5 digits Spindle magnification 0-150% Spindle nagnification 0-150% Spindle output switching Rigid tapping Program input Absolute/incremental instructions Append user macro public variables Fixed loop for drilling Single shape fixed cycle Arc radius R specified	G99 0-200% 0-2,000 mm/min F0, 50100%

	(,-)/////		
User macro			
Decimal point input/Calculator dec Coordinate offset direct input	imal point input		
Any Angle chamfer/corner R	4		
Maximum instruction value	Earth 9 digit		
Compound fixed loop	9 piece		
Composite fixation cycle II Select program segment Skip	G17,G18,G1		
Parity Check	04 digit		
Plane selection	N8 digit		
Subroutine instruction call	10 layers of nestin		
Paper tape code	EIA RS422/IS084		
FANUC10/11 System paper tape	G52-G5		
User software capacity	61		
Macro actuator Tool function/tool compensation			
Automatic tool compensation			
Tool compensation value The mea	asurement value is entered		
Tool function			
Tool shape/wear compensation			
Tool life Management	G43,G44,G49		
Tool radius compensation Tool position offset 128 pairs	G43,G44,G49		
Number of tool compensation			
Tool life management extension			
Program Editing			
Background editing			
Extension editing			
Number of login programs 1000ea Program editing	3		
Program Protection			
Program storage capacity 2 M			
Setup and display			
Show actual speed			
Display alarm information			
Show alarm history Show current location			
Display the floppy disk directory			
Displays the actual spindle rotation	n number /T code		
Help features			
Display in languages by country			
Show operational history			
Show parameter Settings Show program comment 32,31 ch	paragtore		
Show working hours/number of pa			
Self-diagnostic function			
Servo information screen			
Spindle information screen			
Graphic display cutting path displa Status display	iy		
Clock function			
Parameter checksum function	0,		
Data input/output			
External data input	)		
External key input			
External program number External job number retrieval	1-999		
Input/output of memory card	999		
	CH1.		
Reader/puncher interface	Interface		
RS232C port			
USB port			
Automatic data backup Other			
Start running and the indicator ligh	nte un		
Display unit 10.4 "color LCD/MDI	115 415		
Feed is held and indicator light is	on		
NC and servo ready			
PMC System 0i-PMC			
Ethernet features			
EOP(Easy operation screen)			
Select specifications - Data server			
- Hand wheel feed rollback			
- Dynamic graphics display			
- Operation guide i			
- Operation boot 0i			
- Tool load monitoring			
-CF Card (2GB) -PROFBJS-DP			
	Maximum number of		
-Al Profile control I	preread segments 40		
-PROFINET	The second to		
CC-LINK			
-Al Profile Control II	Maximum number of		
- Fast Ethernet	preread segments 200		
	i .		





Menc. coll.

ITEM	UNIT	GHT 355
Max. turning dia	mm	Ø481
Max truning length	mm	1270
Bar machining dia	mm	Ø102
Chuck dia	mm	Ø381
Spindle motor power	kW	22
Max spindle speed	r/min	2500
Max. spindle torque	N∙m	1123
Tool number	ea.	10

# SUZHOU GUDWAY CNC EQUIPMENT CO.,LTD

Address: Room 418B-35, Building 6, No. 25 Lushan Road, New district, Suzhou, China